


August 29, 2019



**Emergency  
Egress Stair  
Stair 1**

**Emergency  
Egress Stair  
Stair 4**

**Science Center  
Astronomy  
Department  
(Roof and 9th  
Floor  
Mezzanine)**

# **Evacuation Procedures**

**Designated  
Meeting Area**  
  
Courtyard  
Near L.I.S.E

**Secondary Indoor  
Meeting Site**  
  
Northwest  
Building- B1  
Lobby Area


Developed by Science Center  
Building Operations

For more information contact:

**Mark Pimentel**  
Building Manager  
1 Oxford Street

**495-2653**

August 29, 2019



**Emergency Egress Stair Spiral Staircase to 8th floor patio**

**Emergency Egress Stair Stair 1**

Science Center

Statistics Department  
(9th Floor)

# Evacuation Procedures

Developed by Science Center  
Building Operations

For more information contact:

Mark Pimentel  
Building Manager  
1 Oxford Street

**495-2653**

**Designated Meeting Area**

Courtyard  
Near L.I.S.E

**Secondary Indoor Meeting Site**

Northwest  
Building- B1  
Lobby Area